Ministry of Education - Capital Management Branch

School District Information		Health Authority (HA) Information	
SD No.	34	Region	
SD Name	Abbotsford	Contact Name	
SD Contact Name:	Bob Beukers	Contact Phone	
SD Contact Phone:	1-604-897-0499	Report Submitted to HA	
Report Date	March 30/ 2022	Report Submission Date	

Click here to access the School Master List for Facility Names and Facility Codes

SCHOOL FACILITY INFORMATION				TEST INFORMATION					MITIGATION STRATEGY & PUBLIC COMMUNICATION PLAN			ADDITIONAL INFORMATION	
School District Number	Ministry Facility Code	School Facility Name	Year Built	Date of Test (mm/yyyy)	Total Samples	Water Fixture Type	Room Location	Lead Level Result (mg/L)	Exceed Maximum Acceptable Concentrations	Mitigation Strategy Description	Describe Public Communication Plan	Comments	Next Scheduled Date of Testing
34													30-Mar-2
34													30-Mar-2
34													30-Mar-2
34													30-Mar-2
34													30-Mar-2
34													30-Mar-2
34													30-Mar-2
34													30-Mar-2
34													30-Mar-2

SCHOOL FACILITY INFORMATION				TEST INFORMATION						MITIGATION STRATEGY & PUBLIC COMMUNICATION PLAN		ADDITIONAL INFORMATION		
School District Number	Ministry Facility Code	School Facility Name	Year Built	Date of Test (mm/yyyy)	Total Samples	Water Fixture Type	Room Location	Lead Level Result (mg/L)	Exceed Maximum Acceptable Concentrations	Mitigation Strategy Description	Describe Public Communication Plan	Comments	Next Scheduled Date of Testing (mm/yyyy)	Ministry Submission Period
34	3434047	Chief Dan George Middle	1984	Nov-19	7	Water Fountain	R117	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communicat248(s)throughschool dist9466854(r)-9.8 (ic)-9.9 (t)-5.3 (w	average of 2 static sampl IC /P AMCID 95 BDC q791.52 668.16		

SCHOOL FACILITY INFORMATION				TEST INFORMATION						MITIGATION STRATEGY & PUBLIC COMMUNICATION PLAN		ADDITIONAL INFORMATION		
School District Number	Ministry Facility Code	School Facility Name	Year Built	Date of Test (mm/yyyy)	Total Samples	Water Fixture Type	Room Location	Lead Level Result (mg/L)	Exceed Maximum Acceptable Concentrations	Mitigation Strategy Description	Describe Public Communication Plan	Comments	Next Scheduled Date of Testing (mm/yyyy)	Ministry Submission Period
34	3434053	Mountain Elementary	1992	Dec-20	9	Sink	Room 122	0.004	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434053	Mountain Elementary	1992	Dec-20	9	Sink	Room 117	0.003	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434053	Mountain Elementary	1992	Dec-20	9	Sink	Room 108	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434053	Mountain Elementary	1992	Dec-20	9	Water Fountain	Room 159	0.000	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434053	Mountain Elementary	1992	Dec-20	9	Water Fountain	Room 117	0.000	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434053	Mountain Elementary	1992	Dec-20	9	Sink	Room 146	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434053	Mountain Elementary	1992	Dec-20	9	Water Fountain	Room 146	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434053	Mountain Elementary	1992	Dec-20	9	Water Fountain	Room 145	0.000	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434003	Mt Lehman Elementary	1909	Nov-19	6	Water Fountain	115	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434003	Mt Lehman Elementary	1909	Nov-19	6	Water Filling Station	R113	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434048	Prince Charles Elementary	1984	Nov-19	5	Water Fountain	Room 21	0.004	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434048	Prince Charles Elementary	1984	Nov-19	5	Water Fountain	Room 25	0.004	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434052	Rick Hansen Sr. Secondary	1993	Dec-20										

SCHOOL FACILITY INFORMATION				TEST INFORMATION						MITIGATION STRATEGY & PUBLIC COMMUNICATION PLAN		ADDITIONAL INFORMATION		
School District Number	Ministry Facility Code	School Facility Name	Year Built	Date of Test (mm/yyyy)	Total Samples	Water Fixture Type	Room Location	Lead Level Result (mg/L)	Exceed Maximum Acceptable Concentrations	Mitigation Strategy Description	Describe Public Communication Plan	Comments	Next Scheduled Date of Testing (mm/yyyy)	Ministry Submission Period
34	3434032	Ross Elementary	1962	Nov-19	5	Water Filling Station	RoomNov-SRoomRoo5(t)5.3.3.0018.2006Tw1.1	148 0 f148BDC s -0.00hC 13.2u005 Tw 1.148 0 f14860 f148BDC .148 0 09 Tc 0.lv01 Tw 1.g				Tw 1s -0.00 09 Tc 0.ndC 13.2oom		

SCHOOL FACILITY INFORMATION					TEST INFORMATION				MITIGATION STRATEGY & PUBLIC COMMUNICATION PLAN	ADDITIONAL INFORMATION
School District Number	Ministry Facility Code	School Facility Name	Year Built	Date of Test (mm/yyyy)	Total Samples	Water Fixture Type	Room Location	Lead Level Result (mg/L)	Exceed Maximum	